

When changing mechanism parts, apply the specified grease to areas marked "xx" as shown in the drawing.

This exploded view diagram illustrates the assembly of a mechanical device. The components are numbered 1 through 127. Key parts include a main housing (101), a circular base (122), a motor or actuator (102), and a control panel (103) with components CN701, CN702, and CN703. A separate assembly (104) is shown with components 106, 107, 108, 109, and 110. A small circuit board (CN781) is also depicted. The diagram uses dashed lines to show the alignment and assembly sequence of the various parts.